Oil Field Environmental Incident Summary

Incident: 20150902083911 Date/Time of Notice: 09/02/2015 08:39 Responsible Party: HESS BAKKEN INVESTMENTS II, LLC HESS BAKKEN INVESTMENTS II, LLC Well Operator: Well Name: EN-DOBROVOLNY A- 155-94-2413H-7 Field Name: MANITOU Well File #: 28099 **Date Incident: 9/1/2015** Time Incident: 09:15 Facility ID Number: County: **MOUNTRAIL Twp:** 155 **Rng:** 94 Sec: 24 Qtr: **Location Description:** Submitted By: Alex Beach Received By: Contact Person: Jason Henry 3015 16th St. SW, Suite 20 Minot, ND 58701 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil Distance Nearest Occupied Building: 0.8 Mile Distance Nearest Water Well: 0.8 Mile Type of Incident Valve/Piping Connection Leak Release Contained in Dike Yes - On Constructed Well Site Reported to NRC: No **Spilled** Units Recovered Units Followup **Units** Oil

Brine 2 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time. All released fluids remained onsite.

Action Taken or Planned:

An approved remediation contractor will be contacted. All impacted material will be cleaned up and disposed of.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 9/2/2015 Status: Reviewed; O&G Lead Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.